

Radiation Testing

Type of Radiation Surveys

- Electromagnetic fields (induction heaters, RF sealers)
- Ultraviolet radiation
- X-ray Shielding design and inspection
- Lasers inspections and safety programs

Standards exist for many types of radiation. Testing equipment can be used to measure the levels at any given point.



A Holaday Instruments ELF Field Strength meter is used to measure both the electric and magnetic fields from a source of concern.



A Ludlum Frisker can be used to look for ionizing radiation such as radioactive contamination in metal from outside Canada